

1. Background information

| SGS order No.: | IN-SUZ-5801-24151 | | | | | | | |
|----------------------|--|------------------|--------------|---|--------------------|--|--|--|
| Coordinator: | Linda Yan | | Telephone: | 0512-62988255 | | | | |
| Description of | commodity (Name, Mo | odel ,Quantity . |) | | | | | |
| Furnace top co | over 2PCS | | | | | | | |
| | | | | | | | | |
| Buyer(Name ,Address) | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| Seller(Name ,A | (ddress) | | | | | | | |
| CHNZBTECH | CO.,LTD. | | | | | | | |
| No. 58, Youche | egang Road, Hexing Stre | eet, Jinfeng To | wn, Zhangjia | gang City | | | | |
| P/I No. | NA | | | | | | | |
| LC No. | NA | | | | | | | |
| Others | Drawing No.: C.0001.E.217-M2010/DLZ001 | | | | | | | |
| | Item | Satisfactory | | N | Non conforming | | | |
| | Quantity check(not include | • | | | | | | |
| | weight check) | | | | | | | |
| Nature of | - , | | | | Subject to | | | |
| inspection: | Item | Satisfactory | Non conform | ing Rejected | buyer's evaluation | | | |
| | Dimension check | | | | • | | | |
| | | | | t to the second | | | | |

2. Instrument

During the inspection, the following instrument calibration status has been checked for inspection:

| No. | Name | ID No. | Measuring range | Calibrated ^{[1] [2]} (Yes/No/NA) | Certificate NO. |
|-----|----------------------|--------|-----------------|---|-----------------|
| 1 | Steel measuring tape | NA | 0~10 M | NO | NA |
| 2 | Callipers | NA | 0~25 MM | NO | NA |

[1] Calibrated

--- "Yes" means the instrument was calibrated and now is in the period of validity.



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at https://www.sgs.com/en/terms-and-conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Block 2C, OET Park, No.69 Weixin Road, SIP, Suzhou, PRC China 215000 中国·江苏·苏州市工业园区唯新路69号一能科技园2C 邮编: 215000 t (86-512) 6298 8251 sgs.china@sgs.com t (86-512) 6298 8251